

To: William Graff
hotline@AmericanTCB.com
From: Andrew Leimer
Andrew.Leimer@fcc.gov
FCC Equipment Authorization Branch

Re: FCC ID: TAI0000TB1

Applicant: TracMe Beacons Pty Ltd
Correspondence Number: 40535
731 Confirmation Number: TC307507
Date of Original E-Mail: 07/10/2007

Subject: This is a Part 95B device - Not a Personal Locator Beacon (95K)

1) The US Coast Guard has requested that the applicant change the Description field from Personal Locator Beacon to a description of the applicants choosing that is more representative of the device. The description, "Personal Locator Beacon" (PLB), is an equipment class for Part 95K devices. This is a Part 95B device. The US Coast Guard and the FCC feel that this is a misrepresentation of the device and could result in confusion with safety-of-life Part 95K PLBs. Please modify the description to something other than Personal Locator Beacon. Please advise.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal pursuant to Section 2.917(c).

DO NOT Reply to this email by using the Reply button. In order for your response to be processed expeditiously, you must upload your response via the Internet at www.fcc.gov, E-Filing, OET TCB/Accreditor Electronic Filing, TCB Login, Submit Correspondence. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

To: Joe Rainczuk
arainczuk@razlin.com
From: Andrew Leimer
Andrew.Leimer@fcc.gov
FCC Equipment Authorization Branch

Re: FCC ID: TAI0000TB1

Applicant: TracMe Beacons Pty Ltd
Correspondence Number: 40537
731 Confirmation Number: TC307507
Date of Original E-Mail: 07/10/2007

Subject: This is a Part 95B device - Not a Personal Locator Beacon (95K)

1) The US Coast Guard has requested that the applicant change the Description field from Personal Locator Beacon to a description of the applicants choosing that is more representative of the device. The description, "Personal Locator Beacon" (PLB), is an equipment class for Part 95K devices. This is a Part 95B device. The US Coast Guard and the FCC feel that this is a misrepresentation of the device and could result in confusion with safety-of-life Part 95K PLBs. Please modify the description to something other than Personal Locator Beacon. Please advise.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal pursuant to Section 2.917(c).

DO NOT Reply to this email by using the Reply button. In order for your response to be processed expeditiously, you must upload your response via the Internet at www.fcc.gov, E-Filing, OET TCB/Accreditor Electronic Filing, TCB Login, Submit Correspondence. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

To: David Lee
david@mflom.com
From: Andrew Leimer
Andrew.Leimer@fcc.gov
FCC Equipment Authorization Branch

Re: FCC ID: TAI0000TB1

Applicant: TracMe Beacons Pty Ltd
Correspondence Number: 40536
731 Confirmation Number: TC307507
Date of Original E-Mail: 07/10/2007

Subject: This is a Part 95B device - Not a Personal Locator Beacon (95K)

1) The US Coast Guard has requested that the applicant change the Description field from Personal Locator Beacon to a description of the applicants choosing that is more representative of the device. The description, "Personal Locator Beacon" (PLB), is an equipment class for Part 95K devices. This is a Part 95B device. The US Coast Guard and the FCC feel that this is a misrepresentation of the device and could result in confusion with safety-of-life Part 95K PLBs. Please modify the description to something other than Personal Locator Beacon. Please advise.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal pursuant to Section 2.917(c).

DO NOT Reply to this email by using the Reply button. In order for your response to be processed expeditiously, you must upload your response via the Internet at www.fcc.gov, E-Filing, OET TCB/Accreditor Electronic Filing, TCB Login, Submit Correspondence. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.